





Completed seismic remediation to make the dike earthquake safe, and worked to control water seepage.



seplaced 2,300 feet of 28 feet wide timber flume with 18 foot wide concrete flume, repaired sections of existing concrete flume



MT. RAINIER



Replaced the rotting apron on the structure to add stability and protect fish



Lower Conveyor Assessment and Tunnel Intake Inspected intake tunnel, forebay and penstocks; replaced intake trash rack with new steel 45 feet across and 53 feet high and made new stop logs; decommissioned Penstock No. 4.


FISH SCREENS

CE CONCRETE PIPE

FLUME

BUCKLEY

NOUR STANDFIFES



Inspected system, refurbished relief valves; repaired discharge tunnels.





DAM TO LAKE TAPPS 7% MILES DAM TO END OF TAIL RACE 14 MILES